



Date: Job No.: 23-1048
2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW




Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LE-01_23-1048.dwg Layout tab: L 1-0 30x42




EXISTING TREE LEGEND

SYMBOL	TREE NAME	SYMBOL	TREE NAME
**************************************	WASHINGTONIA ROBUSTA MEXICAN FAN PALM	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	WASHINGTONIA FILIFERA CALIFORNIA FAN PALM
	CHAMAEROPS HUMILIS MEDITERRANEAN FAN PALM		

PLANTING DISPOSITION LEGEND





EXISTING TURF TO REMAIN (TYP.)




TAG: DESCRIPTION:


EXISTING PUMP STATION TO BE REMOVED




EXISTING SIGN TO BE REPLACED



EXISTING RAILING TO BE REPLACED




EXISTING SHOWER TO BE REPLACED



CONSTRUCTION OPERATION HOURS, PHASING SEQUENCE, AND CONSTRUCTION SCREENING AND SAFETY FENCE LOCATION.

- 2. THERE SHALL BE OPEN AND CLEAR EMERGENCY ACCESS ROUTE / PATH OF TRAVEL ALL TIME DURING CONSTRUCTION.
- 3. CONTRACTOR SHALL FIELD VERIFY ALL EXISTING UTILITIES ON PROJECT SITE, AND SHALL NOTIFY IMMEDIATELY TO LANDSCAPE ARCHITECT AND CLIENT REPRESENTATIVE OF ANY CONFLICT WITH NEW DESIGN LAYOUT PRIOR TO DEMOLITION AND CONSTRUCTION.



KEY MAP






Job No.: 23-1048 2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW

MISSION LANDSCAPE ARCHITECTURE



Emerald Bay - Landscape Plan LAGUNA BEACH, CALIFORNIA, 92651




















SYMBOL	TREE NAME	SYMBOL	TREE NAME
**************************************	WASHINGTONIA ROBUSTA MEXICAN FAN PALM	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	WASHINGTONIA FILIFERA CALIFORNIA FAN PALM


PLANTING DISPOSITION LEGEND



DEMOLITION LEGEND

EXISTING PATHWAY LIGHTING TO BE REPLACED





KEY MAP





Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LE-01_23-1048.dwg Layout tab: LE 2-0 30x42

2023.11.30 OWNER REVIEW





SYMBOL	TREE NAME	SYMBOL	TREE NAME
**************************************	WASHINGTONIA ROBUSTA MEXICAN FAN PALM	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	WASHINGTONIA FILIFERA CALIFORNIA FAN PALM
*	CHAMAEROPS HUMILIS MEDITERRANEAN FAN PALM		POHUTUKAWA NEW ZEALAND CHRISTMAS TREE
	CUPRESSUS CYPRESS		

PLANTING DISPOSITION LEGEND


SYMBOL	TYPE
	EXISTING SHRUB/GROUNDCOVER TO BE REMOVED
	EXISTING SHRUB/GROUNDCOVER TO REMAIN (TYP.)
	EXISTING TURF TO BE REMOVED
	EXISTING TURF TO REMAIN (TYP.)

	EXISTING TURF TO BE REMOVED EXISTING TURF TO REMAIN (TYP.)
DEMO	LITION LEGEND

TAG: DESCRIPTION:

STING RAILING TO BE REPLACED	777777
STING PATHWAY LIGHTING TO BE REPLACED	








$\sqrt{7}$	EXISTING CONCRETE PATHWAY TO BE REPLACE
\ / /	AT EVICTING CONCEPTE LOUITO

1. CONTRACTOR SHALL COORDINATE WITH OWNER'S REPRESENTATIVE FOR CONSTRUCTION OPERATION HOURS, PHASING SEQUENCE, AND CONSTRUCTION SCREENING AND SAFETY FENCE LOCATION.

- THERE SHALL BE OPEN AND CLEAR EMERGENCY ACCESS ROUTE / PATH OF TRAVEL ALL TIME DURING CONSTRUCTION.
- CONTRACTOR SHALL FIELD VERIFY ALL EXISTING UTILITIES ON PROJECT SITE, AND SHALL NOTIFY IMMEDIATELY TO LANDSCAPE ARCHITECT AND CLIENT REPRESENTATIVE OF ANY CONFLICT WITH NEW DESIGN LAYOUT PRIOR TO DEMOLITION AND CONSTRUCTION.





KEY MAP



Job No.: 23-1048 2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW






Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LE-01_23-1048.dwg Layout tab: LE 3-0 30x42





SYMBOL | TREE NAME | SYMBOL | TREE NAME WASHINGTONIA ROBUSTA
MEXICAN FAN PALM WASHINGTONIA FILIFERA CALIFORNIA FAN PALM PHOENIX DACTYLIFERA DATE PALM CUPRESSUS CYPRESS

PLANTING DISPOSITION LEGEND



DEMOLITION LEGEND



TAG: DESCRIPTION:




EXISTING SIGN TO BE REPLACED




PROTECT IN PLACE:



EXISTING DATE PALMS (4) TO RECEIVE SEASONAL HOLIDAY LIGHTING





KEY MAP



Job No.: 23-1048 2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW


MISSION LANDSCAPE ARCHITECTURE







Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LE-01_23-1048.dwg Layout tab: LE 4-0 30x42











KEY MAP





Job No.: 23-1048 2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW




15 GAL. PER PLAN

1 GAL.









Date: Job No.: 23-1048
2023.11.02 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW

Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LC-01_23-1048.dwg Layout tab: LC 2-0 30x42

@ 4`-0" O.C.

5 GAL. @ 4`-0" O.C.


1 GAL. PER PLAN

5 GAL. @ 4`-0" O.C.


5 GAL.
















EXISTING TREE LEGEND



Job No.: 23-1048 2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW







Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LC-01_23-1048.dwg Layout tab: LC 3-0 30x42





SYMBOL	TREE NAME	SYMBOL	TREE NAME
**************************************	WASHINGTONIA ROBUSTA MEXICAN FAN PALM	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	WASHINGTONIA FILIFERA CALIFORNIA FAN PALM
(•)	CUPRESSUS CYPRESS	*	PHOENIX DACTYLIFERA DATE PALM

LEGEND


TAG: DESCRIPTION:


NEW ALUMINUM SIGN WITH WHITE LETTERS TO MATCH EXISTING

- REFER TO IMAGERY

SEASONAL HOLIDAY LIGHTING ON (4) EXISTING DATE PALMS
- REFER TO IMAGERY











Job No.: 23-1048 2023.11.02 OWNER REVIEW 2023.11.04 OWNER REVIEW 2023.11.21 OWNER REVIEW 2023.11.30 OWNER REVIEW

KEEP GATE CLOSED

Please shower & remove all sand before entering the pool & spa

Guests must be accompanied by a resident at all times
 Lap pool reserved for lap swimming 5am-10am daily

MISSION LANDSCAPE ARCHITECTURE

Use pool at your own risk





LC 4-0



ERIOGONUM FASCICULATUM CALIFORNIA BUCKWHEAT



HETEROMELES ARBUTIFOLIA TOYON




LEYMUS CONDENSATUS GIANT WILD RYE



NASSELLA CERNUA NODDING NEEDLEGRASS



SALVIA LEUCOPHYLLA PURPLE SAGE



THIS RENDERING IS AN ARTISTIC RENDITION OF THE DESIGN. IT IS NOT MEANT TO BE AN EXACT RENDITION. SOME ITEMS MAY NOT BE STANDARD AND/OR COULD DIFFER



 Date:
 Job No.: 23-1048

 2023.11.02
 OWNER REVIEW

 2023.11.04
 OWNER REVIEW

 2023.11.21
 OWNER REVIEW


 2023.11.30
 OWNER REVIEW



Emerald Bay - Landscape Plan LAGUNA BEACH, CALIFORNIA, 92651



Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LR-00_23-1048.dwg Layout tab: LR 1-0 30x42



THIS RENDERING IS AN ARTISTIC RENDITION OF THE DESIGN. IT IS NOT MEANT TO BE AN EXACT RENDITION. SOME ITEMS MAY NOT BE STANDARD AND/OR COULD DIFFER



 Date:
 Job No.: 23-1048

 2023.11.02
 OWNER REVIEW

 2023.11.04
 OWNER REVIEW

 2023.11.21
 OWNER REVIEW

 2023.11.30
 OWNER REVIEW



Path: P:\2023\23-1048_Emerald Bay HOA-LS Masterplan\03-CAD\03.01-CS-Concept_Schematic\03.01.01-Sheets File: LR-00_23-1048.dwg Layout tab: LR 2-0 30x42